

PO Box 51 North Newton KS, office@inspections316.com www.inspections316.com

# **Home Inspection Report**

**Prepared For:** 

Dan & Cindy Epp PO Box 51 North Newton 67117

October 17, 2021

**Report # Sample** 



**Certified Member of The American Society Of Home Inspectors** 

# **OVERVIEW**

The overall condition of this home is normal for its age, with a good for it age overall foundation and structure and recent improvements to the roof.

Several conditions were observed that could use improvement, those listed below are the ones that in my opinion are most important. Please read the details on the appropriate page. This is not an all inclusive list, please read the entire report.

Please feel free to call if you have questions. Thanks!

# Dan Epp

Home Inspections @ 316 LLC

Summary of Repair or Maintenance Items:	
*damage under window wrap page	e 4
*door beams tied up page	e 4
*seepage comments page	e 8
Not Inspected	

\*general limitations are listed in the "inspection agreement"

**Aging Systems** 

\*water heater (2005) \*air conditioner (2005) Thank you for selecting us to inspect this home. Your report is broken down into categories which should make it easier to read and understand. The following condition definitions are used throughout the report for the various components of the house.

- ✓ **Functional** Item appears to be functioning properly at the time of inspection.
- ✓ Marginal Item is currently performing it's intended function, but due to it's age and/or condition, long term service should not be expected. Also used for items built to less than normal construction standards.
- ✓ Problem Noted Item is not operating, is in poor condition, or is considered a safety hazard.
- ✓ Maintenance Used for items needing minor repairs or general maintenance.
- ✓ N.A. / N.I. These initials stand for not applicable (NA) to the house and not inspected (NI)

### **General Information**

Bldg. Type: Main entry faces:	*Single Family *East	# of Stories: Bedrooms:	*2 *6	Weather/Temp. People Present:	*Clear / 67° *Owner
Year Built:	*1938	Baths:	*3	-	
Con. Class:	*Frame	Estimated Sq.Feet:	*2500		
Foundation:	*Basement	House Occupied:	*Yes		

### **Grounds & Drainage**

2) M 3) Pr	<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>				Downspout Extensions: *Yes d (partial) Yard Light Type: *Electric crete / Gravel				
1	2	3	4	ITEM	COMMENTS				
x				General Drainage	Rainwater Drainage Drainage away from the house appears to be good on all sides. The downspouts on the gutters have good extensions to move roof water away from the house. This is very important in preventing seepage and foundation problems. Keep the gutters				
x				Drainage @ Dwelling					
x				Gutters/Downspouts					
	x			Sidewalks/Driveway	clean, you may consider gutter guards to make that job easier.				
	x			Concrete / Paver Patio	Trip Hazard				
x				Fence	The concrete patio has settled over the years, leaving ledges that could be a trip hazard. This is a potential liability, and should be corrected. Lifting the slab,				
x				Sprinklers	installing mortar to smooth out the ledge, or replacement of the section are your				
x				Yard Lights	options.				
x				Trees & Shrubs					

### Lawn Sprinklers / Well

The lawn sprinklers were run through a manual cycle and each zone was checked to make sure sprinklers came on and the heads were not damaged. Underground pipes are not visible for inspection. Water is provided by a well, the zone valves are located in underground boxes, the control box is located by the well.

### Lifted Sidewalks

The concrete sidewalk in front and side of the house has a couple of sections that are lifted by tree roots, creating a trip hazard. This is a potential liability that may eventually be your responsibility (the city does not pay for walks and can force you to replace them). Replacement of the affected sections is about the only option.

							Roofing	
<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>			Primary Shingle: *H No. of Layers: *1 Estimated Age: *0	On roof leritage Style asphalt -5 years 5-30 years	Roof Style: Roof Pitch: Valley Type: Other Roofing Types: Chimney Type:	*Gable *Average *Cut valleys *Metal on lean too *Brick		
1	2	3	4	ITEM	COMMENTS			
х				Primary Roofing	Shingles			
х				Valleys	e	1	, often known as a "Heritage" style. c more like a wood roof. The	
х				Flashings		, 8	better wind and hail resistance.	
х				Plumbing Vents	The shingles are in	normal condition with no	visible storm damage All tabs	
x				Other Roofing	The shingles are in normal condition with no visible storm damage. All tabs checked are sealed down, flashings around projections are water tight.			
x				Chimney (above roof)				
x				Roof Deck				

# Attic & Roof Structure

2) M 3) P	<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>			Method of Inspection: Location of Access: Insulation Type (s): Thickness / R-Value: Vapor Barrier?	*Blo	llway hatch own fiberglass -12" / R-30	Roof Framing Method: Sheathing Type: Attic Vent Types: Power Attic Vent? Whole House Fan?	*2x4 rafters on 24" centers *Wafer board sheathing *Rooftop / Gable *No *No
1	2	3	4	ITEM			COMMENT	S
x				Roof Framing	No problems were noted with the structure, insulation, or ventilation in the attic			
x				Roof Sheathing		No active leaks we	ere noted.	
x				Attic Insulation				
x				Attic Ventilation				
x				Water Stains / Leaks				
NA				Power Fans				

2) M 3) P1	1) Functional 2) Marginal 3) Problem Noted 4) Maintenance			Wall Insulation: <sup>2</sup> Siding Types: <sup>2</sup> Trim Type: <sup>2</sup>	*Yes *Viny *Wraj		Window Type: Glass: Storm Windows? Door Types: Door Bell?	*Wood double hung *Single pane *Yes *Wood & aluminum *NA		
1	2	3	4	ITEM			COMMEN	TS		
х				Exterior Wall Structu	ıre	General The exterior walls and components are in good condition, and will require ver				
х				Siding						
x				Brick / Stone		little paint maintenance. The siding requires no painting, the trim pieces on windows and facia boards are wrapped in metal, and the windows are in good condition.				
x				Trim						
x				Facia & Soffit				various locations. No repairs are		
х				Paint & Caulking		needed but wanted to poi	nt it out.			
	х			Windows / Trim		Windows				
х				Doors / Trim		Under some of the window wrap we noted damage to sills. Options are to maintain them by caulking seams, or replace damaged sills.				
х				Doorbell						
NA				Wood Deck						
х				Porch / Railing / Step	os					

Garage

### Garage Type: 1) Functional \*Single detached \*Fiberglass Door Type: 2) Marginal Floor: \*Concrete Door Opener? \*Yes 3) Problem Noted Roof Type: \*Same as house \*Light beam & Pressure reversal **Reversing Method:** 4) Maintenance Estimated Age: \*Same as house \*Shed Other Buildings: 2 3 4 1 ITEM **COMMENTS** Structure х Door Reversal Beam The door reversal beam system is designed to reverse the door if anything х Concrete interrupts the light beam between the two receivers. These receivers are supposed to be on each side of the door, about 6 inches from the ground. In this case, they Roofing х were installed above the opener pointing at each other, which is an improper Garage Door х installation. Moving them to the proper position is recommended. The door did reverse when I applied pressure, but the beam is better for pets and small Opener/Safety Test х children. Other Structures х

Garage

The garage has some problems typical of an older structure. The floor has settled and cracked, the walls lean, the garage door opening is out of square. Correcting these issues can be expensive, contact a general contractor if you want to make improvements. As it is, the building is functional.

### **Exterior Walls**

# **Interior Rooms / Bathrooms**

2) M 3) Pi	) Marginal Floors:			Floors: *Tile	*Tile / Carpet / Wood / Vinyl Bath #2: *2nd floor / full bath with tile shower			
1	2	3	4	ITEM	COMMENTS			
x				Walls/Ceilings	Interior Inspections			
x				Floor Coverings	Interior inspections include checking walls and ceilings for cracks and stains, testing accessible outlets for proper wiring and polarity, operating lights and ceiling fans, operating accessible doors and windows, and checking the floorings for			
х				Light Fixtures/Fans				
х				Smoke Alarms	obvious problems. Furniture and personal property is not disturbed, so not all the floors and walls are always visible.			
х				Window Function				
х				Doors	Plaster On the main floor walls and ceilings are finished with lath and plaster, and there are			
х				Stairways/Rails	cracks present in most rooms. Plaster cracks are related to sagging and settlement			
х				Bath Walls/Ceilings	of the structure over the years, and from the weight of the plaster itself. Repairs can be done, but if the plaster is loose on the lath it may have to be removed and			
х				Bathroom Ventilation	replaced.			

# Kitchen & Utility

<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>			Counter Tops: ' Dishwasher: ' Oven: ' Range Hood: '	*Average *Solid surface *Built in *Gas *Vented *NA	Laundry Facilities Location: Dryer Power Source: Laundry vent: Laundry sink:	*Basement *Gas *Outside *Yes		
1	2	3	4	ITEM		COMMENTS		
x				Cabinets / Counters	Kitchen Inspections			
x				Flooring/Finishes	Kitchen inspections include r outlets, checking cabinets and			
x				Sink & Plumbing	testing the oven and exhaust	fans. Refrigerators, microv	waves, and other portable	
NA				Disposal	appliances are not tested. Th	e washer and dryer are not	tested.	
x				Oven / Range				
x				Exhaust Hood				
x				Dishwasher				
x				Laundry Room				

### Wood or Gas Burning Appliances & Chimneys

2) M 3) Pi	1) Functional 2) Marginal 3) Problem Noted 4) Maintenance			Fuel:*NChimney Type:*N	Masonry NA Masonry Yes	Other: Fuel: Chimney Type: Chimney Cap?	*Manufactured gas fireplace *Natural Gas *Metal direct vent *Yes	
1	2	3	4	ITEM		COMMENTS		
x				Main Floor	Fireplace Not in Use The fireplace used to have a gas burning standing appliance, with the exhaust go up a masonry chimney. The appliance is gone, and the gas is shut off. This will			
x				Basement				
x				Gas Starter	never be a wood bu	urner, and only with alteration	is to the chimney could it be used	
NA				Damper	for gas burning logs or appliances.			
x				Chimney / Flue Liner				
x				Chimney Cap				

Gas Fireplace / Basement

The fireplace is a modern natural gas burning unit, with a sealed firebox and outside combustion air. The gas valve is located in the lower section of the fireplace, the switch to turn on the flames located on the wall. It has a standing pilot flame that can be turned off in the summer. The unit was run for about ten minutes, no problems were noted.

-								
2) M 3) Pr	<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>			Septic Location: *NA	lic Drain pipe type: *Plastic nt yard Gas pipe type: *Black			
1	2	3	4	ITEM	COMMENTS			
x				Main Water Shutoff	General No leaks were noted from the visible supply and drain pipes, pressure was goo to the fixtures even with more than one on at the same time, and the pipes appear to be supported well where needed. No opinions can be offered on underground supply and sewer pipes, they are hidden from view.			
x				Water Pressure				
x				Supply Pipes				
x				Drain Pipes / Vents				
x				Gas Piping	Aging Water Heater			
x				Water Heater & Flue	The water heater is functioning properly at this time, but is nearing the end of a normal life expectancy and should be monitored closely for leaks around the			
x				Exterior Hose Faucets	bottom of the tank.			
x				Sump Pump / Drain Tiles	Sumps			
NA				Lift Pump	1) There is an exterior sump and pump with drain tiles on the SE corner of the			
x				Water Well	<ul><li>house in the garden next to house.</li><li>2) There is a sump in the basement by the furnace. This was installed to pick</li></ul>			
x				Toilets	up ground water during high rain events, when the water table in the			
x				Sinks	neighborhood gets higher than the basement floor.			
x				Tubs & Showers				

## **Plumbing System & Water Heater**

### **Air Conditioning System**

2) M 3) Pi	1) Functional 2) Marginal 3) Problem Noted			Estimated Age: Fuel:	*Rheem *2005 *Electricity	Evaporator Location: Condenser Location:	*Furnace Mount *North side
4) M	lainter	nance	;		*Conventional Split System	Incoming Temp:	*75 degrees
	Compressor Size: *			Compressor Size:	*3 tons	Outgoing Temp:	*55 degrees
1	2	3	4	ITEM		COMMENTS	
x				General Operation	Operation		
x				Exterior Condenser			g out of the ducts were in the the coils on the outside unit.
NI				Evaporator			
x				Freon Lines			
x				Condensate Line			

Aging Unit

The air conditioner unit has reached or surpassed the normal life expectancy (15-20 years). Older units may require more repairs as they get older, and I cannot predict how long it will last. Make sure it is checked yearly.

### **Heating System**

<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>			System Type:*Central ForFuel:*Natural GaManufacturer:*RheemEstimated Age:*2005Chimney Type:*Plastic sideDistribution:*Galvanized	As Filter Type: *Disposable Location: *Beside furnace Size: *75,000 btu e wall Other Heat: *NA				
1	2	3	4	ITEM	COMMENTS			
х				General Operation	Inspection Methods			
x				General Maintenance	This is a modern furnace with automatic pilot flame lighting and a fan assisted exhaust system. The furnace access panels were removed and all			
x				Burners	visible component parts checked. With this type of furnace, the heat			
х				Exhaust System	exchangers are not visible without dismantling the furnace.			
х				Combustion Air	Operation			
х				Fan and Motor	The furnace is running properly, no problems were noted.			
х				Filter				
х				Gas Lines/Valves				
х				Distribution / Ductwork				
х				Thermostat				
х				Heat Source in Each Room?				
х				Humidifier				

Humidifier Maintenance

Humidifiers are a high failure system, and need to be checked regularly. Replacement of the evaporator pad should be done at least every other year. Listen for water flow when the system is running, the electric water valve is easily clogged. Make sure you check the housing of the unit for mold growth and wipe it clean as needed. Open the air flow damper for the winter, close it in the summer, and always turn off the unit in the summer. We recommend running it at 40-50% in the winter.

								<b>Electrical System</b>		
2) M 3) P1	unctio largin cobler lainte	al n Not		Service Enters:*OverhadWire Type/Size:*#2 copVolts:*120/24Capacity*100 andService Ground:*GroundMain Disconnect?*Yes		opper 240 volt amps	Main Panel Type/Location: Sub Panels / Location: Circuit wiring: Receptacles: GFCI Receptacles:	*Breakers / Stairway *NA *Copper Romex *Grounded & Ungrounded *Yes		
1	2	3	4	ITEM			COMM	MENTS		
х				Service Entrance		System Insp				
х				Service Ground			ical system inspections include removing the distribution panel covers and ning wiring and overcurrent protection devices, checking as many outlets			
х				Main Panel		as possible for proper wiring and grounding, operating lights and fans, and				
NA				Other Panels		examinir	ng exposed circuit wires.			
х				120 Volt Circuit Wiri	ing	Outlets				
х				240 Volt Circuit Wiri	ing			mbination of 2 & 3-hole (ungrounded) and 3-hole The grounded outlets are found in the key areas (sinks and and represent a good upgrade.		
х				Outlets / Switches		(U	2			
х				Fans / Fixtures						
х				Exterior Items						

## Foundation & Floor Structure

<ol> <li>Functional</li> <li>Marginal</li> <li>Problem Noted</li> <li>Maintenance</li> </ol>				Foundation Type:*BasementConstruction Type*Concrete BI*Poured Construction Joist Support:*Block BeariFloor Joists:*2x8 joists onFloor Decking:*Solid board	crete ng wall		
1	2	3	4	ITEM	COMMENTS		
x				Foundation Walls	General		
x				Support Walls / Beams	The visible portions of the basement walls are in good overall condition for there age, with no signs of significant movement or tilting.		
x				Floor Joists	for there age, with no signs of significant movement of thing.		
x				Floors Level?			
x				Concrete Floor			
x				Basement Finishes			
	х		x	Seepage / Moisture Problems			

Seepage

Owners stated some (minor) seepage in the basement storage room, also during very high rain events, high water table has pushed water through floor in the basement living areas. A interior sump was added to help with this issue, since adding have not had issues. While I make no promises about future seepage, you can help minimize it by making sure the gutters are always clean, the extensions are on the downspouts, and the grade outside is sloping away from the house.